

4

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VI

ALLIED BANK TOWER AT FOUNTAIN PLACE 1445 ROSS AVENUE

DALLAS, TEXAS 75202

DATE: 8/2/88

SUBJECT: FIT TASK REQUEST FROM: DAVID COK (6H-ES) DAVE WINEMAN (6E-SH)

Martha M. McKee, Chief

riease task ril to complete the following work:	☐ New Assignment ☐ Amendment	
Key EPA Contact. NameDAVIDTCODIC	_	
SSID Number: CERID Number: 64 6KD9807 50319		
EPA Site Name: AIR CENTER INC. 98	9831259	
City/County/State. OKLA. /OKLA.		
Desired Report Format: Desired Report Standard Report Other (Specify). Letter Report Formal Briefing		
Type of Activity. PA PHRS Support Enforcement Support General Technical Assistance St Special Studies ESI		
General Task Description: REVISE PRELIMINARY HRS PER HTTACH	IED	
INSTRUCTIONS / COMMENTS.		
	· · · · · · · · · · · · · · · · · · ·	
Specific Elements:		
SEE ATTACHED COMMENTS		
Additional Scope Attached		
CONCURRENCE:		

Jo Ann Miller

Regional QA Review Comments for Air Center Inc.-Wiley Post Preliminary HRS Package (OKD980750319) August 1, 1988

<u>General</u> - Update preliminary HRS package (including: narrative summary, score work sheets, documentation records and references), based upon data collected subsequent to its initial submittal to the EPA.

<u>Specific</u> - First sentence, paragraph two of narrative summary: replace supposedly with allegedly.

- First sentence, paragraph three of narrative summary: ref. 16 does not support information; correct this.
- Based upon a search of EPA CERCLA/RCRA files, identify and describe any nearby facilities which may handle or have handled hazardous wastes similar to those associated with this facility and comment on the potential contribution these sites may have had toward the contamination detected while investigating this facility. Especially of interest should be the Gulfstream Aerospace or Gulfstream American Company.